

**Flood Control Project Maintenance
Levee Inspections****LMA District Cover Sheet****Spring 2013 Levee Inspection Results****Sutter Maintenance Yard Nelson Bend**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2013 Levee Inspection Results

Sutter Maintenance Yard Nelson Bend

Waterway			Bank	Unit Miles
Unit No. 01 Feather River West Levee-Nelson Bend				0.50
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	05/10/2013 - 05/10/2013			
DWR Inspector	Bob Duffey			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Sutter Maintenance Yard Nelson Bend

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Feather River West Levee-Nelson Bend					0.50	05/10/2013 05/10/2013	Bob Duffey	

LMR No.	Levee Mile		Category	Item	Location * + Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End					Start	End	Photo
1	0.00	0.50	Encroachments	CR A/W En	FE : Fence Inspector Comments: A landowner has constructed a gate on the crown that prevents inspection of this unit. The unit was inaccessible for the fall 2012 season and was not inspected. The unit was accessible during the spring 2013 inspection, but was difficult to open and should be monitored.		°	°	7
DWR ID: DWR_ST0006_01_f_2012_7									
2	0.01	0.45	Vegetation	LS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.886937 ° -121.614752 °	38.880822 ° -121.614565 °	1 Y	
DWR ID: DWR_ST0006_01_s_2012_1									
3	0.01	0.45	Trim / Thin Trees	LS M Ma	T2 : Thin trees to allow visibility of the ground and room to flood fight.	38.886933 ° -121.614753 °	38.880857 ° -121.614555 °	3 Y	
DWR ID: DWR_ST0006_01_s_2012_3									
4	0.05	0.05	Vegetation	WS M Ma	V4 : Elderberries are blocking visibility and flood fight capability.	38.886408 ° -121.615092 °	38.886408 ° -121.615092 °	4 Y	
DWR ID: DWR_ST0006_01_s_2012_4									
5	0.13	0.22	Vegetation	WS M Ma	V4 : Elderberries are blocking visibility and flood fight capability.	38.885320 ° -121.615677 °	38.883970 ° -121.615830 °	5	
DWR ID: DWR_ST0006_01_s_2012_5									
6	0.30	0.30	Vegetation	WS M Ma	V4 : Elderberries are blocking visibility and flood fight capability.	38.882870 ° -121.615477 °	38.882870 ° -121.615477 °	6	
DWR ID: DWR_ST0006_01_s_2012_6									
7	0.48	0.48	Encroachments	CR U En	BU : Building	38.880488 ° -121.614230 °	38.880488 ° -121.614230 °	8	
DWR ID: DWR_ST0006_01_s_2012_8									

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2013

Sutter Maintenance Yard Nelson Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River West Levee-Nelson Bend		0.50	05/10/2013 05/10/2013	Bob Duffey

Levee Mile Report Line	2
Start Levee Mile	0.01
End Levee Mile	0.45
Location	Land Side
Category	
Item	Vegetation
This photo was taken at levee mile 0.00 looking downstream at the landside vegetation.	
rduffey_s_20130509_390.JPG	



Levee Mile Report Line	3
Start Levee Mile	0.01
End Levee Mile	0.45
Location	Land Side
Category	
Item	Trim / Thin Trees
Trim the trees up 5 feet to allow visibility.	
rduffey_s_20130513_391.JPG	



Levee Mile Report Line	4
Start Levee Mile	0.05
End Levee Mile	0.05
Location	Water Side
Category	
Item	Vegetation
View of the elderberries that are blocking visibility.	
rduffey_s_20130513_392.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---